/ CHECKING CONDITIONS HOISTING DEVICE CONDITION DE VERIFICATION APPAREIL DE LEVAGE


UN CERTIFICAT DE CONFORMITE AUX NORMES DES APPAREILS DE LEVAGE DEVRA ETRE OBLIGATOIREMENT JOINT A CHAQUE OUTILLAGE. CE CERTIFICAT SERA DELIVRE PAR UN ORGANISME AGREE.

A CERTIFICATE OF COMPLIANCE TO THE HOISTING-DEVICE STANDARDS MUST BE ATTACHED COMPULSORILY TO EACH TOOL. THE CERTIFICATE SHALL BE ISSUED BY AN APPROVED ORGANIZATION.

EN STATIQUE / STATISTICALLY :

= 165 daN $= (55x2) \times 1,5$

L



ADDED TABLE OF SCHEDULED FOLLOW-UP, IT.022 AND IT.023, DELETED IT.015, UPDATED MARKING

AJOUTE TABLEAU DE SUIVI PERIODIQUE, REP.022 ET REP.023 SUPPRIME REP.015 + MIS A JOUR MARQUAGE

MODIFIE REP.001, REP.002, REP.011, OTE. REP.013 (2 ->4), AJOUTE REP.017, REP.018, REP.018, REP.020, ET REP.021, AJOUTE REP.017, REP.018, REP.020, ET REP.020, TABLEAU "CONSIGNES GENERALES" ET NOTA SUR PL.16 MODIFIED IT. 001, IT.002, IT.011 0TE. IT.013 (2 -->4) ADDED IT IT.017, IT.018, IT.019, IT.020 AND IT.021, TABLE "GENERAL REGULATIONS" AND MOTE ON PL.116

AJOUTE TRADUCTION EN ANGLAIS - MODFIFIE REP.001, 002, 011 ENGLISH TRANSLATION ADDED - MODIFIED IT.001, 002, 0

Isometrique View Vue isométrique Echelle : 1:3 Scale

12

MODIFIE REP.001 A 006(MATIERE AUAG → 8060) - REDESSINE EN DAO MODIFIED IT. 001 10 006 (MATERIAL AU4G ---> 6060) - REDRAM IN CAD

MODIFICATIONS

MODIFIE REP.001 ET 002 - AJOUTE REP.015 ET 016 ET CHARGE DEPREUVE. MODIFIED IT.001 AND 002 - ADDED IT.015, 016 AND PI

MASSE DE

Αg

ALL DIMENSIONS ARE IN MILLIMETERS

E DE L'OUTILLAGE: 2.8 TOOL WEIGHT: 2,8 Kg

| | 270 |
|------|--------|
| | SR |
| 270 | M |
| SR | ALA |
| TE | SE |
| CTI | ITE |
| E LO | 007 |
| YPE | 7 × |
| - | 207 |
| FOR | A |
| ET | HRE |
| FIL | H |
| NI | HIG |
| FRE | H |
| AU | IM |
| EB | ING |
| COLL | BOND |
| / | |

ZONE DE MARQUAGE DU N° D'IMMATRICULATION OUTILLAGE SUIVANT GUIDE DE PRODUCTION UPIO19 TOOL MARKING AREA P/N AS PER UPIO19 PRODUCTION GUIDE

LES COTES ET CRITERES DU PLAN REPERES 🖯 SONT TRANSCRIRE SUB LE "CERTIFICAT DE CONFORMITE" THE DIMENSIONS AND CRITERIA OF THE DRAWING INDICATED WHIT 🖯 MUST BE COPIED ON THE "CERFICATE OF COMPLIANCE"

07650-10

NLM

VOIR DETAIL
REFER TO DETAIL
STD

SCREW H M10
ECROU A EMBASE M10
BASE NUT M10

600 800 000

6 011

SANS OBJET NOT APPLICABLE PROCESS: FONCTION: ADAPTATION PERMETTANT LE RETOURNEMENT DU GENERATEUR FUNCTION: ADJUSTEMENT FOR TURNING-OVER OF GENERATOR

VOIR DETAIL
REFER TO DETAIL
VOIR DETAIL
REFER TO DETAIL
ALLEGER 6060

VOIR DETAIL
REFER TO DETAIL
VOIR DETAIL
REFER TO DETAIL

ALL LEGER 6060

5 004

5 003

REF.N°0X4.8

GOBIN DAUDE

024

900 900

| PLATINE RIGHT PL | PLATINE LEFT PLA | DESIG | | S | ILLOO NO | TAT | TII | ST LA PR | TED WI | | FORMA | 212 |
|---------------------|--------------------------------|---------------------------------|---------------------------------------|--|---|---|--|---|------------------------------------|----------------------------------|------------------------------|--------------|
| 1 PI | 1 PL | QUANT | DESSINE PAR. DRAWN BY: SETA MCD | LE D6/03/06 MACHINE! ENGINE | ARRIUS 2 DESIGNATION OUTII | ADAPTAT | PIVOTI | CE DESSIN EST LA PR | THIS DRAWING IS COMMUNICATED WI | ECHELLE | 1/2 | P |
| 200 | 100 | REP | 9 | E twai | os o | | CAT | 47 TA | eles nws | auissə | o uer | 970 |
| 4 | m | P. S. P. | | | 1 | | | 1 | | | | _ |
| 9570691330 | | | | 227420 | 227497 | 251965 | | 03320-08x20 | | + + | | |
| MT NO | VOIR DETAIL REFER TO DETAIL | VOIR DETAIL REFER TO DETAIL | STD | BRADY | BRADY | BRADY | STD | NLM . | VOIR DETAIL REFER TO DETAIL | STD | STD | STD |
| | PLAQUETTE GAUCHE LEFT PLATE | PLAQUETTE DROITE RIGHT PLATE | VIS H M10-16 SCREW H M10-16 | PICTOGRAMME PIC 215 Ø25 PICTOGRAPH PIC 215 Ø25 | PICTOGRAMME PIC 254 Ø25 PICTOGRAPH PIC 254 Ø25 | PICTOGRAMME PIC 467 Ø25 PICTOGRAPH PIC 467 Ø25 | GOUPILLE ELASTIQUE Ø2 LG:15 SPRING PIN Ø2 LG:15 | GOUPILLE CYLINDRIQUE Ø8 LG:20 CYLINDRICAL PIN Ø8 LG:20 | PLAQUETTE PLATE | VIS CHc M6-10 SCREW CHC M6-10 | RONDELLE L 10 WASHER L 10 | VIS H M10-20 |
| | - | - | 2 | 2 | 2 | 2 | 2 | 60 | 2 | 2 | 4 | 2 |
| | 023 | 022 | 021 | 020 | 910 | 018 | 017 | 016 | 910 | 014 | 013 | 012 |
| | ω | 60 | | | | | | | 60 | | | |

TION DE RETOURNEMENT

ST2100

APPROVED BY: SETA POH

GNATION / DESCRIPTION

REGULATIONS GENERAL ES CONSIGNES GENERAL

- PORTER LES EQUIPEMENTS INDIVIDUELS DE SECURITE
- . WEAR INDIVIDUAL SAFETY EQUIPMENT
- NE PAS UTILISER L'OUTILLAGE HORS DE SA PERIODE DE VALIDITE
- . DO NOT USE A TOOL BEYOND ITS VALIDITY DA
- AVANT UTILISATION :
- LAGE CORRESPONDE A LA TACHE A REALISER DE L'OUTILLAGE (USURE, FISSURES, - VERIFIER QUE LA REFERENCE DE L'OUTILLAGE CORRESPONDE A LA TACHE A REALISER - VERIFIER VISUELLEMENT L'ETAT GENERAL DE L'OUTILLAGE (USURE, FISSURES, PIECES MANQUANTES, ...)
 - PRENDRE CONNAISANCE DU PROCESS D'UTILISATION DE L'OUTILLAGE (VOIR NOTA B)

BEFORE USE :

- MAKE SURE THE TOOL PIN AGREES WITH THE TASK TO BE DONE
 DO A VISUAL INSPECTION OF THE TOOL GENERAL CONDITION (WEAR, CRACKS, MISSING PARTS, ...)
 READ THE USE PROCESS OF THE TOOL (REFER TO NOTE B)
- SI ENDOMMAGE : SIGNALER LES ANOMALIES SI CORRECT : STOCKER L'OUTILLAGE DANS UNE ZONE APPROPRIEE HORS RISQUES L'ETAT DE L'OUTILLAGE APRES UTILISATION, VERIFIER VISUELLEMENT
- TOOL CONDITION: AFTER USE, DO A VISUAL INSPECTION OF THE
- APPROPRIATE, SAFE AREA - IF DAMAGED : REPORT THE ANOMALIES - IF CORRECT : STORE THE TOOL IN AN

| VOMINAL TOLERANCE |
|-------------------|
| |

PLANCHE SHEET

